~ TX-470

FACT SHEET

VELSICOL CHEMICAL CO. - Beaumont, Texas

(TXD067261412)

Primary product is the herbicide dicamba.

NPDES PERMIT REVIEW

TX 0003671

Exp.

June 20, 1978 December 31, 1980

Effluent Limitations

- Permit does not limit the quantity of dicamba in the effluent as prescribed in the Pesticide Manufacturing Guidelines.
 (40 CFR 455, FR April 25, 1978 - Revised September 29, 1978).
- 2. The NPDES Regulations (40 CFR 122.41, FR June 7, 1979) requires that the pollutant discharge rate be reduced if part of the discharged process water is disposed of into a well or into a POTW.

Monitoring Requirements

- 1. Composite sampler at outfall is not adequate.
- 2. Some of the analytical test procedures were not followed as prescribed.

TOXIC/HAZARDOUS POLLUTANT ASSESSMENT

Sand freduced

1. This plant uses or produces the following toxic pollutants:

90068976



SUPERFUND FILE

SEP 1 0 1992

REORGANIZED

1,2,4-trichlorobenzene, toluene, 2,4-dichlorophenol, and methyl chloride.

The process water effluent contained the following: 2.

Pollutant	ug/1	Pollutant	ug/l
Toluene	3	Arsenic	2
Trichloroethane	18	Chromium	15
Dicamba	1110	Copper	5

The concentration of dicamba exceeds the Pesticide Manufacturing Guideline limit.

Toxic compounds in the air samples were in the range of 1-40 μg/m³. Blank samples contained many of the same compounds at the same concentrations.

Miller Health of Sides